


01606 271830

Issue Type Chart Summary Report

### Issue Type across network



	0	0.0%
CrossPath	1,011	18.3%
Intimidating	53	1.0%
IntimidatingOrMisleading	7	0.1%
LandUse	241	4.4%
Maintain	2,433	44.0%
Misleading	83	1.5%
Missing	281	5.1%
Obstacles	84	1.5%
Other	414	7.5%
Terrain	245	4.4%
Vegetation	677	12.2%
Total:	5,529	100.0%




01606 271830


**Issue Type Chart Summary Report** 

Admin Group: Chester

# Issue Type across network

For Aldersey





#### Admin Area:

#### **Aldersey**

Maintenance Type:	Number of Occurences:
CrossPath/Electric fence	1
CrossPath/Fence/Hedge/Wall	1
LandUse/Building	1
Maintain/Gate/Bridle/Steel/1Way	1
Maintain/Gate/Field/Steel	3
Maintain/Gate/Field/Steel/2in1/Pedestrian	1
Maintain/Other/Gap	1
Maintain/Stile/OneStep	1
Maintain/Stile/Two+Step	1
Obstacles/General	2
Total:	13





01606 271830

**Issue Type Chart Summary Report** 

# **Issue Type across network**

For Aldford





#### Admin Area: Aldford

Maintenance Type:	Number of Occurences:
CrossPath/Fence/Hedge/Wall	9
CrossPath/Watercourse	1
LandUse/Crops	8
LandUse/Ploughed	1
Maintain/Bridge/Other	1
Maintain/Gate/Field/Steel	1
Maintain/Gate/Pedestrian/Timber	1
Maintain/SignNotRoad/WM Post/General	1
Maintain/SignRoad/Fpost/Metal	1
Maintain/Stile/OneStep	4
Maintain/Stile/Two+Step	3
Other/MappingProblem	2
Terrain/Other	, 1
Vegetation/Sides&Above	1
Vegetation/Surface	10
Total:	45





01606 271830

**Issue Type Chart Summary Report** 

### Issue Type across network

For Ashton Hayes





#### Admin Area:

#### **Ashton Hayes**

Maintenance Type:	Number of Occurences:	
	0	
CrossPath/Fence/Hedge/Wall	7	
LandUse/Building	1	
Maintain/Gate/Field/Steel	1	
Maintain/Gate/KissingGate/Steel/Standard	1	
Maintain/SignNotRoad/Fpost/Metal	1	
Maintain/SignNotRoad/WM Post/General	2	
Maintain/Stile/OneStep	7	
Misleading/Sign	1	
Obstacles/General	2	
Other/MappingProblem	2	
Terrain/Muddy	2	
Vegetation/Surface	, · 1	
Total:	28	





01606 271830

**Issue Type Chart Summary Report** 

## Issue Type across network

For Backford





Admin Area:	Backford

Maintenance Type:	Number of Occurences:
CrossPath/Electric fence	2
CrossPath/Fence/Hedge/Wall	5
CrossPath/General	1
Maintain/Bridge/Timber/6Metre	1
Maintain/Gate/Field/Steel	2
Maintain/SignRoad/Fpost/Wood	1
Maintain/Stile/OneStep	5
Maintain/Stile/Two+Step	4
Misleading/Sign	1
Obstacles/Deposit	1
Other/MappingProblem	1
Terrain/Crossfall	1
Terrain/Muddy	2
Vegetation/Sides&Above	6
Total:	33





01606 271830

**Issue Type Chart Summary Report** 

## Issue Type across network

For Barrow





Admin Area: Barro	WC
-------------------	----

Maintenance Type:	Number of Occurences:
CrossPath/Electric fence	4
CrossPath/Fence/Hedge/Wall	6
CrossPath/General	1
CrossPath/Watercourse	2
Intimidating/Sign	2
LandUse/Building	1
Maintain/Bridge/Sleeper/3Metre	2
Maintain/Gate/Field/Steel	3
Maintain/Gate/KissingGate/Timber	2
Maintain/Oate/RissingGate/Timber	
Maintain/SignNotRoad/Fpost/Wood	2
Maintain/Steps/Concrete	4
	4
Maintain/Stile/Dog	1
Maintain/Stile/OneStep	11
Maintain/Stile/Two+Step	13
Misleading/Sign	1
Missing/Sign/NotRoad	2
Missing/Sign/Roadside	2
Obstacles/General	1
Obstacles/Machinery	1
Obstacles/Other	2
Other/FlyTipping	1
Other/MappingProblem	6



01606 271830

### **Issue Type Chart Summary Report**

Total:	91	
Vegetation/Surface	1	
Vegetation/Sides&Above	5	
Vegetation/Fallen Tree	1 *	
Vegetation/Bough	2	
Terrain/Waterlogged	5	
Terrain/Muddy	3	





01606 271830

**Issue Type Chart Summary Report** 

## Issue Type across network

For Barton





#### Admin Area:

#### Barton

Maintenance Type:	Number of Occurences:
Maintain/Stile/OneStep	2
Maintain/Stile/Two+Step	5
Missing/Sign/Roadside	2
Other/MappingProblem	3
Vegetation/Sides&Above	2
Total:	4.4





01606 271830

**Issue Type Chart Summary Report** 

# Issue Type across network

For Beeston





P	10	m	in /	\re	a:

#### Beeston

Maintenance Type:	Number of Occurences:
CrossPath/Electric fence	1
CrossPath/Fence/Hedge/Wall	16
CrossPath/Watercourse	3
LandUse/Building	2
LandUse/Crops	6
LandUse/Forestry Plantation	2
LandUse/Ploughed	3
Maintain/Bridge/Sleeper/3Metre	1
Maintain/SignNotRoad/Fpost/Wood	1
Maintain/SignRoad/Fpost/Wood	3
Maintain/Stile/Dog	2
Maintain/Stile/OneStep	8
Maintain/Stile/Two+Step	13
Missing/Sign/Roadside	3
Other/MappingProblem	2
Terrain/Other	1
Terrain/Waterlogged	1
Vegetation/Sides&Above	7
Vegetation/Surface	2
Total:	77





01606 271830

**Issue Type Chart Summary Report** 

## Issue Type across network

For Bickley





#### Admin Area:

### **Bickley**

Maintenance Type:	Number of Occurences:		
CrossPath/Electric fence	. 1		
CrossPath/Fence/Hedge/Wall	5		
CrossPath/Watercourse	1		
LandUse/Crops	2		
Maintain/Bridge/Sleeper/3Metre	1		
Maintain/Gate/Field/Timber	. 1		
Maintain/SignRoad/Fpost/Wood Maintain/Stile/OneStep Maintain/Stile/Two+Step	1 4 3		
		Missing/Sign/Roadside	2
		Other/MappingProblem	1
Vegetation/Sides&Above	7		
Vegetation/Surface	1		
Total:	30		