

NOTE: - Roads scoring 100 or greater are identified for inclusion in the winter treatment network.

AHG	Roads Identified	Parish	Final risk assessment score	Comments	Outcome of review
Congleton	Moss Lane	Sandbach	0	The bus route turns off and travels down Salt Line Way. There is nothing of note along the remainder of Moss Lane. However, there is the small industrial estate to the north (Norton Way) off Moss Lane, which has been scored at 25.	Not included
Congleton	Church Bank	Goostrey	0	This road travels north off the pre-salt route, which in turn links onto the rural road network. All of which have scored zero. There is nothing along the section that falls within the criteria set on the scoring matrix.	Not included
Crewe	Colleys Lane	Wistaston	0	Both sections of Colleys lane score zero. There are a alternatives route to the southwest (A51 Nantwich Bypass) and northeast (Wistaston Green Road) which are recommended for inclusion on the precautionary network.	Not included
Crewe	Wistaston Green Road	Wistaston	100	Risk assessment reviewd and score revised due to bus route and requirement to treat full road length	Added to treatment network
Crewe	Weston Lane	Weston	10	Nothing apart from the bridge deck over the railway bridge. Similarly for Weston Lane, Basford.	Not included
Crewe	Broughton Road	Crewe	25	The northern end of the road is subject to run off from adjacent land which is caused by poorly maintained land drainage systems.	Not included
Crewe	Mablins Lane	Crewe	25	The junction with Parkers Road is subject to run off from adjacent land in extreme weather conditions, only.	Not included
Crewe	Maw Green Lane	Crewe	100	Albeit the road has been scored 100 the spreader can only treat the first section up to the new roundabout. There is no suitable turning area for the section leading to the land-fill site. Beyond the landfill entrance, there is a railway bridge which has an oblique turning and is subject to both width & height restrictions.	Not included
Crewe	Selworthy Drive	Crewe	0	There is nothing along the section that falls within the criteria set on the scoring matrix. Furthermore, there is no suitable turning point for the spreader.	Not included
Macclesfield	Havannah Lane	Eaton	0	There is nothing along the section that falls within the criteria set on the scoring matrix.	Not included
Macclesfield	School Lane	Marton	75	Risk assessment score below threshold. Currently on a secondary route. Score reflects National Cycle Network and urban Primary school (with 30mph zone).	Not included
Macclesfield	Dark Lane	Gawsworth	0	There is nothing along the section that falls within the criteria set on the scoring matrix.	Not included
Macclesfield	Longbutts Lane	Gawsworth	0	Urban unclassified road with a risk assessment score below the required threshold. Cul-de-sac with no suitable turning point.	Not included
Macclesfield	Gawsworth Road	Gawsworth	50	Risk assessment score below threshold	Not included
Macclesfield	Byrons Lane	Macclesfield	125	Risk assessment score reviewed - designated route to Sutton community	Added to treatment network
Macclesfield	Ridge Hill	Sutton	115	Link road between sections of network identified for inclusion on precautionary network. Travel by spreader to rejoin precautionary route	Added to treatment network
Macclesfield	Church Lane	Sutton	150	Link road between sections of network identified for inclusion on precautionary network. Travel by spreader to rejoin precautionary route	Added to treatment network
Macclesfield	High Street	Bollington	100	Risk assessment score reviewed, particularly with reference to the gradient	Added to treatment network
Macclesfield	Lord Street	Bollington	100	Risk assessment score reviewed, particularly with reference to the gradient	Added to treatment network
Macclesfield	Chancery Lane	Bollington	110	Link road between sections of network identified for inclusion on precautionary network. Travel by spreader to rejoin precautionary route (Lord Street to High Street section, only)	Added to treatment network
Macclesfield	Moss Brow	Bollington	125	Link road between sections of network identified for inclusion on precautionary network. Travel by spreader to rejoin precautionary route	Added to treatment network
Nantwich	Queens Drive	Nantwich	200	Link road between sections of network identified for inclusion on precautionary network. Travel by spreader to rejoin precautionary route	Added to treatment network
Nantwich	Monks Lane	Nantwich	100	Compilation of criteria which in total lends the road to be included on the precautionary network - low score bus route, NCN and natural progression of vehicular traffic etc.	Added to treatment network
Poynton	Brookledge Lane	Adlington	100	Risk assessment reviewed and score revised	Added to treatment network
Poynton	Shrigley Road	Pott Shrigley	75	Altitude above 200m and Cat 3 gradient. Risk assessment score below threshold	Not included
Poynton	Mill Lane	Mottram St Andrew	35	Unsuitable for Heavy Goods Vehicles. Risk assessment score below threshold	Not included
Poynton	Anson Road	Poynton	10	Risk assessment score below threshold	Not included
Poynton	Counting House Road	Disley	25	Risk assessment score below threshold	Not included
Poynton	Chantry Road	Disley	25	Risk assessment score below threshold	Not included
Poynton	Redhouse Lane	Disley	35	Risk assessment score below threshold	Not included
Poynton	Light Alders Lane	Disley	25	Risk assessment score below threshold	Not included
Wilmslow	Lincoln Road	Wilmslow	0	There is nothing along the section that falls within the criteria set on the scoring matrix.	Not included
Wilmslow	Tudor Road	Wilmslow	0	There is nothing along the section that falls within the criteria set on the scoring matrix.	Not included
Wilmslow	Heyes Lane	Alderley Edge	75 & 0	Railway Station (Urban Commuter) (75) first 15 m from London Road only. Risk assessment score below threshold	Not included
Wilmslow	Hough Lane	Alderley Edge	0 & 0	There is nothing along the section that falls within the criteria set on the scoring matrix.	Not included
Wilmslow	Chapel Road	Alderley Edge	0	There is nothing along the section that falls within the criteria set on the scoring matrix.	Not included
Wilmslow	Mottram Road	Alderley Edge	50 & 50	Shaded/cold spots scored at 50. Risk assessment score below threshold	Not included
Wilmslow	Chorley Hall Lane	Alderley Edge	35	Risk assessment score below threshold	Not included
Wilmslow	Trafford Road	Alderley Edge	0 & 0	Cat 4 gradient (25) and bridge deck (10) Risk assessment score below threshold	Not included